

PUDDLETOWN AREA PARISH COUNCIL

The Coombe

Due to the nature of the area, the following risk assessment has been carried out from ground level.
The Tree Management Plan should be read in conjunction to this risk assessment.

The following risks have been identified and are being managed by the Puddletown Area Parish Council:

Risks Assessment carried out by	Clerk - Michelle Harrington
Date of Assessment:	December 2024

Subject	Hazard(s)	Who/what may be harmed	Risk L/M/H	Impact L/M/H	Management/ Control of risk already in place
Slope	Unstable ground	Public	H	H	Bank stabilisation work in progress. Area cleared as much as necessary stabilisation matting laid. More trees to be planted to restore the area visually and for root system to help stabilise the bank from underground. Slope is estimated at between 30 ⁰ – 60 ⁰ . In places. Fencing has been erected around steepest section and warning signed added to area.
Trees	Up-rooting, falling	Public	H	H	Hardy Tree Surgeons have investigated and carried out any urgent work to fell unsafe trees. A full details report of the area has been recommended.

End of Document.

Level of Risk: L= Low, M= Medium, H= High

Risk L = Unlikely to happen in 12 months, M = Could happened once or twice in 12 months, H = Could happen more than twice in 12 months.

Impact (Consequence should risk occur): L= Low, M= Medium, H= High

Impact L = Minor Injury does not require medical interaction. M = Moderate, requires medical intervention. H = Major, overnight stay in hospital likely.